
Anderson-Cottonwood Irrigation District **Operations Report** June 12, 2025 — July 3, 2025




River Report

14,000 CFS for Delta needs

Churn Creek Pumps



Main Canal



Crowley Gulch
L/s x .0353147=CFS



-It's been a rough first half!!!!



-Lateral 35 and 29 have been challenging


-Things are smoothing out.

-Magnacide application was a huge turning point.

Main Canal Operations (daily)


- Monitor flows on Supervisory Control and Data Acquisition (SCADA)
 - multiple times daily to keep steady flows
 - adjust flows as needed to follow river changes, pulses, and deliveries
- Monitor automated equipment at Diversion site(SCADA)
- Clean screen at diversion site
 - manual operations of installed equipment
- Inspect/Clean Main canal trash screens
 - -15 total from top to bottom
- Coordinate opening and closing of laterals for scheduled delivery.
 - timing the increase or decrease of flows to maintain as consistent of flows as possible


SCADA Operations



Trash Rake and Fish Screens








Main Canal Trash Screens







Water Operator Daily Operations



Phone Calls



Schedule Deliveries



Check up water



Deliver water



Keep Grilles Clean

Consistent Issues

- -Main canal users taking water without communicating with the Water Operator. Resulting in unplanned drop in flows
- -Customers not turning over on time and delaying an already full schedule
- -Cross fences at property lines that collect debris
- -Livestock damage to ditch banks
- -Finding a work life Balance


Lateral 21.3

- Core bank to repair leaking rodent holes
- No interuption in service
- More water back in the ditch





Lateral 29.2 Repair







Lateral 29

- Worked it back to a 15 day rotation and gaining ground

- Every repair is making a difference
- More land irrigated, faster.

Lateral 35.1 (Driveway job)



Scott Passmore

45 years of service

Happy Retirement!!



Proposed off-season work

(Contractors)

Churn Creek Bottom

- -Reshape/compact Main Canal top to bottom
 - -Freeway Ditch TA to Duncan
 - -Weeks Rd to Peach Ln.
- Freeway Ditch Pipeline 9 leaks in 2000 ft

Main Canal

- -Potential check structures
- -De-veg/Reshape/compact Crowley Gulch to Gas Point Rd (approx. 4100ft)
 - Stopping point of Panorama project to Crowley Gulch (approx. 13,100ft)
 - Bobbin Flume to Ludwig Gulch (approx. 8000 ft)

(Staff) -Broadhurst Rd. to Pecan Ln.

-Lateral 3 Turnout @ N. Bonnieview (design and construct)

Area 21(Anderson)

- De-veg/reshape/compact Lateral 21 S-turn to Deschutes(increase capacity)
- Lateral 21- repair leak @ Deschutes & Balls Ferry

Diversion Facility

- Replace pulleys and cables on fish screen Brushes

Improving efficiency one repair at a time.

Questions or Comments?