




AUGUST MAINTENANCE 2023

WO# 66

Cap broken alfalfa riser



WO# 64

Freeway Ditch CCB

Replace trash grille



WO# 59

School Ditch CCB
Install trash grille



WO# 57

Lateral 3 Main
CCB

Install New 24"
Waterman Gate



Tree Removal

Lateral 3 Main CCB



Tree Removal (Cont.)



Tree Removal

Job Complete

Services Donated by
I-5 Rentals





WO#71 - Lateral 3.4 CCB

Leaking Pipe Repair



WO# 71 Leaking Pipe Repair
(cont.)



WO# 72
Lateral 3 Valve replacement


WO# 70

Replace standing Plank at Crowley



Main Canal:
Tree removal from access
Road





WO# 76
Remove, Mortar and Re-install
18" Waterman Gate